



PINAGEM DE TRANSISTORES


MPSA42




MPSA92



BD139/BD140



TIP41C/TIP42C



ST100P - REV 5.0

TENSAO DE ALIMENTACAO: 42+42VDC
TRANSFORMADOR: 30+30VAC - 5A

TRANSISTORES DRIVERS:


TIP41C (NPN) TIP42C (PNP) - PADRAO
BD139 (NPN) BC140 (PNP) - MONTAR INVERTIDO

FUSIVEIS DE 4 AMPERES

VERIFICADO E DISTRIBUIDO POR



DISTRIBUIDOR OFICIAL DO PROJETO
ADQUIRA SEU KIT COMPLETO NO SITE
WWW.ALFAKITS.COM

Itemref	Quantity	ST100P SUPERSTRONG POWER AMPLIFIER			Article No./Reference	
Designed by PAULO H.	Checked by JEFFERSON W.	Approved by - date - 08/11/2018	Revisao 5.0	Date 27/07/18	Scale 1:1	
 SIGMA ELETRONICA & TECNOLOGIA			ST100P - POWER STAGE			
			APROVADO		Edition 0	Sheet 1/1